A member of
INFLATABLE SAFETY AND
SURVIVAL EQUIPMENT
TRADE ASSOCIATION LIMITED
ISSETTA FORM NO 197

Certificate No. **2829613**

CERTIFICATE OF RE-INSPECTION

This is to certify that the raft detailed below has been surveyed, controlled and tested in compliance with requirements from: **SMA** and the manufacturer and in accordance with IMO resolution **A.761 (18)**

Inflatable Liferaft

Identification:

Type:		Serial Number:	Date of Manufacture:
RFD Surviva Mk IV TO		**5086310222581**	**Sep-2018**
Fabric Type:	Capacity:	Length of Painter:	Max Stowage height:
Polyurethane	**25**	**28** m/inside **0** m/outside	**18** m

Cylinders:

Serial No.	Contents CO2	Contents N2	Latest hyd. test
18w050079	**10.770kg**	**0.540kg**	**Mar-2018**

Equipment:

Unit	Type	Serial No.	Expiry date
Emergency pack:	**Solas B**	**22581**	**Oct-2022**
EPIRB:			
HRU test:			
Radar Reflector:	**Chemring**		
First aid kit:	**RFD CAT.C**	**INT24726**	**Feb-2024**

Unit	Serial No.	Date of Manufacture
Humidity/CO2 Sensor:		

Tests:

Nap-test	Gas inflation test	Floor seam test	Load test davit launched
Yes/No **No**	Yes/No **No**	Yes/No **No**	Yes/No **No**
Latest Test:	Latest Test:	Latest Test:	Latest Test:

Verification:

Date of inspection:	Service Station name and No.	Date issued to ship:
20-Oct-2021	**50403: Survitec Survitec Gothenburg**	**21-Oct-2021**
National Marine authority ID No.	Remarks/modification:	

According to SOLAS regulation, this inflatable liferaft requires servicing within **12** months from the date of inspection (above).

Flagstate of ship: **Sweden**

IMO No.

International call signal

Name of ship: **LINDA AF HELSINGBORG**

Ship owner: **Hartford Rederi AB**

survitec
50403

John Bjørkman

For authorized servicing station

John Björkman

Signature

Survitec Group Limited - Registered Office, 1 – 5 Beaufort Road, Birkenhead, Merseyside, England, CH41 1HQ
Email: info@survitecgroup.com

survitecgroup

SURVITEC LIFE RAFT TEST AND SURVEY REPORT

Date: 2021-10-21 | Station N°: 50403 | Reinspection certificate N°: -

Life raft maker	RFD	Ships name	Linda AF Helsingborg
Type of life raft	Surviva MK IV	Owner	Hartford Rederi AB
Capacity	25	Flag state	Sweden
Serial #	5086310222581	IMO No	-
Pack	Solas B	Last service	09-2020
Date of manufacture	09-2018	Call sign	-
HRU type / n °	-		

OVERPRESSURE VALVE				PRESSURE TEST (WP TEST)					
LOWER		UPPER			Time	T*	A*	Lower buoyancy (millibars)	Upper buoyancy (millibars)
Opening	Reseat	Opening	Reseat	Starting	09:30	18.8	-	231	243
276	231	281	243	End	10:30	19.1	-	228	238
				Difference after correction				-1.81%	-2.55%

T* = Temperature - A* = Atmospheric

Cylinder N°	18w050079
CO2 weight	10.770
N2 weight	0.540
Full weight	31.361
Weight reading	OK
Last hydro test	03-2018
Cylinder refilling	No
OP head type/#	Leafield GIST

Tests done	Yes	No
NAP test		✘
GI test		✘
Floor seam test		✘
Over load test (DL)		✘
Cyl. hydro test		✘
Hoses changed		✘

Main buoyancy	Check	R*
Buoyancy	✔	
Lifeline outer	✔	
Lifeline inner	✔	
Painter patch	✔	
Towing patch	✔	
Bowsing lines	—	
Ramp / Ladder	✔	
OP valves	✔	
OP valves cap	✔	
Labels	✔	
Floating knife	✔	
Sea anchor	✔	
Quoit + line	✔	
Reflective tape	✔	
Signal card	✔	
Immed. actions card	✔	

Canopy	Check	R*
Canopy	✔	
Reflective tape	✔	
Rainwater collector	✔	
Entrances	✔	
External flash light	✔	
Arches	✔	
Shackle (DL)	—	
Webbings (DL)	—	
Container / Valise	**Check**	**R***
Upper shell	✔	
Lower shell	✔	
Foam/Plastic	replacement SE-79056A	✘
Painter line	check 18/28m	✘
Labels	✔	
Identification tube	✔	

Inner floor	Check	R*
Automatic bailer	—	
Vacuum breaker	—	
Insulating foam	✔	
Outer floor	**Check**	**R***
Reflective tape	✔	
Water pockets	✔	
CO2 cylinder pockets	✔	
Righting straps	✔	
Inflation system	**Check**	**R***
Inlet valves	✔	
No return valve arch	—	
No return valve ramp	—	
Hoses	✔	
Inflation valve	✔	

R* = Replacement

Equipment	Check	R*	Expiry date
Pack			
Hand flare	✔		08-2023
Rocket parachute	✔		08-2023
Smoke signal	✔		08-2023
Food	—		
Drinking water	—		
First aid kit	replacement LS-MM004R INT24726	✘	02-2024
Seasickness tablet	replacement 3x LS-MM029R	✘	10-2024
Battery for torch	replacement 4x LS-AM2	✘	
Repair kit (glue) .	✔		10-2022
HRU	—		
Epirb	—		
Outside pack			
Flash light battery	✔		04-2023
Internal light	✔		05-2023
Transponder radar	—		
P.P. Straps	replacement 8x RFD-41423001	✘	
Diaphragm	✔		
Environmental Charge	✔		

Other equipment	Check	R*
Leak stopper	✔	
Bellow	✔	
Bailer	✔	
Sponge	✔	
Tin opener	—	
Fishing kit	—	
Torch	✔	
Spare bulb	✔	
Signal mirror	✔	
Whistle	✔	
Drinking vessel	✔	
Seasickness bag	✔	
Sea anchor	✔	
Paddles	✔	
Rainwater collector	✔	
Servicing history	✔	
T.P.A.	✔	
Radar reflector	check Chemring	✘

Additional	Check	R*
Painter Block	replacement RFD-20883001	✘
Label	replacement RFD-04819001	✘

Additional	Check	R*
Label	replacement 2x RFD-20765001	✘

LIFE RAFT AND EQUIPMENT CONDITION INFORMATION

	Yes	No		Yes	No
Was raft wet?		✘	Was life raft damaged?		✘
Was container damaged?		✘	Had life raft been inflated at sea?		✘

Description:

REPACKING

DOCUMENTS	
Life raft label completed	✔
ID card completed	✔
Reinspection certificate completed	✔

CONNECTIONS	
Flashlight battery connected	✔
Internal light connected	✔
Painter line attached	✔
Controlled by (signature)	Gideon Hayden

DOCUMENTS	
Container label completed	✔
Servicing history completed	✔

FOR LIFE RAFTS EQUIPPED WITH VENTURI	
Venturis opened/secured	—
Flap covers installed	—
Venturis caps removed	—

Station n°: 50403 Technician name: John Björkman Visa: 11577

A member of
INFLATABLE SAFETY AND
SURVIVAL EQUIPMENT
TRADE ASSOCIATION LIMITED
ISSETTA FORM NO 197

Certificate No. **2829612**

CERTIFICATE OF RE-INSPECTION

This is to certify that the raft detailed below has been surveyed, controlled and tested in compliance with requirements from: **SMA** and the manufacturer and in accordance with IMO resolution **A.761 (18)**

Inflatable Liferaft

Identification:

Type:		Serial Number:	Date of Manufacture:
RFD Surviva Mk IV TO		**5086310222579**	**Sep-2018**
Fabric Type:	Capacity:	Length of Painter:	Max Stowage height:
Polyurethane	**25**	**28** m/inside **0** m/outside	**18** m

Cylinders:

Serial No.	Contents CO2	Contents N2	Latest hyd. test
18w051130	**10.770kg**	**0.540kg**	**Mar-2018**

Equipment:

Unit	Type	Serial No.	Expiry date
Emergency pack:	**Solas B**	**22579**	**Apr-2023**
EPIRB:			
HRU test:			
Radar Reflector:	**Chemring**		
First aid kit:	**RFD CAT.C**	**INT24726**	**Feb-2024**

Unit	Serial No.	Date of Manufacture
Humidity/CO2 Sensor:		

Tests:

Nap-test	Gas inflation test	Floor seam test	Load test davit launched
Yes/No **No**	Yes/No **No**	Yes/No **No**	Yes/No **No**
Latest Test:	Latest Test:	Latest Test:	Latest Test:

Verification:

Date of inspection:	Service Station name and No.	Date issued to ship:
20-Oct-2021	**50403: Survitec Survitec Gothenburg**	**21-Oct-2021**
National Marine authority ID No.	Remarks/modification:	

According to SOLAS regulation, this inflatable liferaft requires servicing within **12** months from the date of inspection (above).

Flagstate of ship: **Sweden**

IMO No.

International call signal

Name of ship: **LINDA AF HELSINGBORG**

Ship owner: **Hartford Rederi AB**

survitec
50403

John Bjørkman

For authorized servicing station

John Björkman

Signature

Survitec Group Limited - Registered Office, 1 – 5 Beaufort Road, Birkenhead, Merseyside, England, CH41 1HQ
Email: info@survitecgroup.com

survitecgroup

SURVITEC LIFE RAFT TEST AND SURVEY REPORT

Date: 2021-10-21 | Station N°: 50403 | Reinspection certificate N°: -

Life raft maker	RFD	Ships name	Linda AF Helsingborg
Type of life raft	Surviva MK IV	Owner	Hartford Rederi AB
Capacity	25	Flag state	Sweden
Serial #	5086310222579	IMO No	-
Pack	Solas B	Last service	09-2020
Date of manufacture	09-2018	Call sign	-
HRU type / n °	-		

OVERPRESSURE VALVE				PRESSURE TEST (WP TEST)					
LOWER		UPPER			Time	T*	A*	Lower buoyancy (millibars)	Upper buoyancy (millibars)
Opening	Reseat	Opening	Reseat	Starting	09:30	18.8	-	234	239
278	234	269	239	End	10:30	19.1	-	231	234
				Difference after correction				-1.79%	-2.59%

T* = Temperature - A* = Atmospheric

Cylinder N°	18w051130
CO2 weight	10.770
N2 weight	0.540
Full weight	31.248
Weight reading	OK
Last hydro test	03-2018
Cylinder refilling	NO
OP head type/#	Leafield GIST

Tests done	Yes	No
NAP test		✘
GI test		✘
Floor seam test		✘
Over load test (DL)		✘
Cyl. hydro test		✘
Hoses changed		✘

Main buoyancy	Check	R*	Canopy	Check	R*	Inner floor	Check	R*
Buoyancy	✔		Canopy	✔		Automatic bailer	—	
Lifeline outer	✔		Reflective tape	✔		Vacuum breaker	—	
Lifeline inner	✔		Rainwater collector	✔		Insulating foam	✔	
Painter patch	✔		Entrances	✔		**Outer floor**	**Check**	**R***
Towing patch	✔		External flash light	✔		Reflective tape	✔	
Bowsing lines	—		Arches	✔		Water pockets	✔	
Ramp / Ladder	✔		Shackle (DL)	—		CO2 cylinder pockets	✔	
OP valves	✔		Webbings (DL)	—		Righting straps	✔	
OP valves cap	✔							
Labels	✔		**Container / Valise**	**Check**	**R***	**Inflation system**	**Check**	**R***
Floating knife	✔		Upper shell	✔		Inlet valves	✔	
Sea anchor	✔		Lower shell	✔		No return valve arch	—	
Quoit + line	✔		Foam/Plastic	replacement SE-79056A	✘	No return valve ramp	—	
Reflective tape	✔		Painter line	check 18/28m	✘	Hoses	✔	
Signal card	✔		Labels	✔		Inflation valve	✔	
Immed. actions card	✔		Identification tube	✔				

R* = Replacement

Equipment	Check	R*	Expiry date
Pack			
Hand flare	✔		08-2023
Rocket parachute	✔		04-2023
Smoke signal	✔		08-2023
Food	—		
Drinking water	—		
First aid kit	replacement LS-MM004R INT24726	✘	02-2024
Seasickness tablet	replacement 3x LS-MM029R	✘	10-2024
Battery for torch	replacement 4x LS-AM2	✘	
Repair kit (glue)	✔		10-2023
HRU	—		
Epirb	—		
Outside pack			
Flash light battery	✔		04-2023
Internal light	✔		07-2023
Transponder radar	—		
P.P. Straps	replacement 8x RFD-41423001	✘	
Diaphragm	✔		
Environmental Charge	✔		

Other equipment	Check	R*
Leak stopper	✔	
Bellow	✔	
Bailer	✔	
Sponge	✔	
Tin opener	—	
Fishing kit	—	
Torch	✔	
Spare bulb	✔	
Signal mirror	✔	
Whistle	✔	
Drinking vessel	✔	
Seasickness bag	✔	
Sea anchor	✔	
Paddles	✔	
Rainwater collector	✔	
Servicing history	✔	
T.P.A.	✔	
Radar reflector	check Chemring	✘

Additional	Check	R*
Painter Block	replacement RFD-20883001	✘
Label	replacement RFD-04819001	✘

Additional	Check	R*
Label	replacement 2x RFD-20765001	✘

LIFE RAFT AND EQUIPMENT CONDITION INFORMATION

	Yes	No		Yes	No
Was raft wet?		✘	Was life raft damaged?		✘
Was container damaged?		✘	Had life raft been inflated at sea?		✘

Description:

REPACKING

DOCUMENTS	
Life raft label completed	✔
ID card completed	✔
Reinspection certificate completed	✔

CONNECTIONS	
Flashlight battery connected	✔
Internal light connected	✔
Painter line attached	✔
Controlled by (signature)	Gideon Hayden

DOCUMENTS	
Container label completed	✔
Servicing history completed	✔

FOR LIFE RAFTS EQUIPPED WITH VENTURI	
Venturis opened/secured	—
Flap covers installed	—
Venturis caps removed	—

Station n°: 50403 Technician name: John Björkman Visa: 11577

A member of
INFLATABLE SAFETY AND
SURVIVAL EQUIPMENT
TRADE ASSOCIATION LIMITED
ISSETTA FORM NO 197

Certificate No. **2829632**

CERTIFICATE OF RE-INSPECTION

This is to certify that the raft detailed below has been surveyed, controlled and tested in compliance with requirements from: **SMA** and the manufacturer and in accordance with IMO resolution **A.761 (18)**

Inflatable Liferaft

Identification:

Type:		Serial Number:	Date of Manufacture:
RFD Surviva Mk IV TO		**5086310222562**	**Sep-2018**
Fabric Type:	Capacity:	Length of Painter:	Max Stowage height:
Polyurethane	**25**	**28** m/inside **0** m/outside	**18** m

Cylinders:

Serial No.	Contents CO2	Contents N2	Latest hyd. test
18w052103	**10.770kg**	**0.540kg**	**Mar-2018**

Equipment:

Unit	Type	Serial No.	Expiry date
Emergency pack:	**Solas B**	**22562**	**Oct-2022**
EPIRB:			
HRU test:			
Radar Reflector:	**Chemring**		
First aid kit:	**RFD CAT.C**	**INT24726**	**Feb-2024**

Unit	Serial No.	Date of Manufacture
Humidity/CO2 Sensor:		

Tests:

Nap-test	Gas inflation test	Floor seam test	Load test davit launched
Yes/No **No**	Yes/No **No**	Yes/No **No**	Yes/No **No**
Latest Test:	Latest Test:	Latest Test:	Latest Test:

Verification:

Date of inspection:	Service Station name and No.	Date issued to ship:
20-Oct-2021	**50403: Survitec Survitec Gothenburg**	**21-Oct-2021**
National Marine authority ID No.	Remarks/modification:	

According to SOLAS regulation, this inflatable liferaft requires servicing within **12** months from the date of inspection (above).

Flagstate of ship: **Sweden**

IMO No.

International call signal

Name of ship: **LINDA AV HELSINGBORG**

Ship owner: **Hartford Rederi AB**

survitec
50403

John Bjørkman
For authorized servicing station

John Björkman
Signature

Survitec Group Limited - Registered Office, 1 – 5 Beaufort Road, Birkenhead, Merseyside, England, CH41 1HQ
Email: info@survitecgroup.com

survitecgroup

SURVITEC LIFE RAFT TEST AND SURVEY REPORT

Date: 2021-10-21	Station N°: 50403	Reinspection certificate N°: -

Life raft maker	RFD	Ships name	Linda AF Helsingborg
Type of life raft	Surviva MK IV	Owner	Hartford Rederi AB
Capacity	25	Flag state	Sweden
Serial #	5086310222562	IMO No	-
Pack	Solas B	Last service	09-2020
Date of manufacture	09-2018	Call sign	-
HRU type / n °	-		

OVERPRESSURE VALVE				PRESSURE TEST (WP TEST)					
LOWER		UPPER			Time	T*	A*	Lower buoyancy (millibars)	Upper buoyancy (millibars)
Opening	Reseat	Opening	Reseat	Starting	09:30	18.8	-	241	236
278	241	271	236	End	10:30	19.1	-	239	232
				Difference after correction				-1.75%	-2.20%

T* = Temperature - A* = Atmospheric

Cylinder N°	18w052103
CO2 weight	10.770
N2 weight	0.540
Full weight	31.723
Weight reading	OK
Last hydro test	03-2018
Cylinder refilling	NO
OP head type/#	Leafield GIST

Tests done	Yes	No
NAP test		✘
GI test		✘
Floor seam test		✘
Over load test (DL)		✘
Cyl. hydro test		✘
Hoses changed		

Main buoyancy	Check	R*	Canopy	Check	R*	Inner floor	Check	R*
Buoyancy	✔		Canopy	✔		Automatic bailer	—	
Lifeline outer	✔		Reflective tape	✔		Vacuum breaker	—	
Lifeline inner	✔		Rainwater collector	✔		Insulating foam	✔	
Painter patch	✔		Entrances	✔		**Outer floor**	**Check**	**R***
Towing patch	✔		External flash light	✔		Reflective tape	✔	
Bowsing lines	—		Arches	✔		Water pockets	✔	
Ramp / Ladder	✔		Shackle (DL)	—		CO2 cylinder pockets	✔	
OP valves	✔		Webbings (DL)	—		Righting straps	✔	
OP valves cap	✔							
Labels	✔		**Container / Valise**	**Check**	**R***	**Inflation system**	**Check**	**R***
Floating knife	✔		Upper shell	✔		Inlet valves	✔	
Sea anchor	✔		Lower shell	✔		No return valve arch	—	
Quoit + line	✔		Foam/Plastic	replacement SE-79056A	✘	No return valve ramp	—	
Reflective tape	✔		Painter line	check 18/28m	✘	Hoses	✔	
Signal card	✔		Labels	✔		Inflation valve	✔	
Immed. actions card	✔		Identification tube	✔				

R* = Replacement

Equipment	Check	R*	Expiry date
Pack			
Hand flare	✔		08-2023
Rocket parachute	✔		04-2023
Smoke signal	✔		08-2023
Food	—		
Drinking water	—		
First aid kit	replacement LS-MM004R INT24726	✘	02-2024
Seasickness tablet	✔		11-2022
Battery for torch	replacement 4x LS-AM2	✘	
Repair kit (glue)	✔		10-2022
HRU	—		
Epirb	—		
Outside pack			
Flash light battery	✔		04-2023
Internal light	✔		05-2023
Transponder radar	—		
P.P. Straps	replacement 8x RFD-41423001	✘	
Diaphragm	✔		
Environmental Charge	✔		

Other equipment	Check	R*
Leak stopper	✔	
Bellow	✔	
Bailer	✔	
Sponge	✔	
Tin opener	—	
Fishing kit	—	
Torch	✔	
Spare bulb	✔	
Signal mirror	✔	
Whistle	✔	
Drinking vessel	✔	
Seasickness bag	✔	
Sea anchor	✔	
Paddles	✔	
Rainwater collector	✔	
Servicing history	✔	
T.P.A.	✔	
Radar reflector	check Chemring	✘

Additional	Check	R*	Additional	Check	R*
Painter Block	replacement RFD-20883001	✘	Label	replacement 2x RFD-20765001	✘

LIFE RAFT AND EQUIPMENT CONDITION INFORMATION

	Yes	No		Yes	No
Was raft wet?		✘	Was life raft damaged?		✘
Was container damaged?		✘	Had life raft been inflated at sea?		✘

Description:

REPACKING

DOCUMENTS	
Life raft label completed	✔
ID card completed	✔
Reinspection certificate completed	✔

CONNECTIONS	
Flashlight battery connected	✔
Internal light connected	✔
Painter line attached	✔
Controlled by (signature)	Gideon Hayden

DOCUMENTS	
Container label completed	✔
Servicing history completed	✔

FOR LIFE RAFTS EQUIPPED WITH VENTURI	
Venturis opened/secured	—
Flap covers installed	—
Venturis caps removed	—

Station n°: 50403 Technician name: John Björkman Visa: 11577

A member of
INFLATABLE SAFETY AND
SURVIVAL EQUIPMENT
TRADE ASSOCIATION LIMITED
ISSETTA FORM NO 197

Certificate No. **2829621**

CERTIFICATE OF RE-INSPECTION

This is to certify that the raft detailed below has been surveyed, controlled and tested in compliance with requirements from: **SMA** and the manufacturer and in accordance with IMO resolution **A.761 (18)**

Inflatable Liferaft

Identification:

Type:		Serial Number:	Date of Manufacture:
RFD Surviva Mk IV TO		**5086310222561**	**Sep-2018**
Fabric Type:	Capacity:	Length of Painter:	Max Stowage height:
Polyurethane	**25**	**28** m/inside **0** m/outside	**18** m

Cylinders:

Serial No.	Contents CO2	Contents N2	Latest hyd. test
18w051102	**10.770kg**	**0.540kg**	**Mar-2018**

Equipment:

Unit	Type	Serial No.	Expiry date
Emergency pack:	**Solas B**	**22561**	**Oct-2022**
EPIRB:			
HRU test:			
Radar Reflector:	**Chemring**		
First aid kit:	**ZOD CAT.C**	**210226**	**Sep-2024**

Unit	Serial No.	Date of Manufacture
Humidity/CO2 Sensor:		

Tests:

Nap-test	Gas inflation test	Floor seam test	Load test davit launched
Yes/No **No**	Yes/No **No**	Yes/No **No**	Yes/No **No**
Latest Test:	Latest Test:	Latest Test:	Latest Test:

Verification:

Date of inspection:	Service Station name and No.	Date issued to ship:
20-Oct-2021	**50403: Survitec Survitec Gothenburg**	**21-Oct-2021**
National Marine authority ID No.	Remarks/modification:	

According to SOLAS regulation, this inflatable liferaft requires servicing within **12** months from the date of inspection (above).

Flagstate of ship: **Sweden**

IMO No.

International call signal

Name of ship: **LINDA AV HELSINGBORG**

Ship owner: **Hartford Rederi AB**

survitec
50403

John Bjørkman

For authorized servicing station

John Björkman

Signature

Survitec Group Limited - Registered Office, 1 – 5 Beaufort Road, Birkenhead, Merseyside, England, CH41 1HQ
Email: info@survitecgroup.com

survitecgroup

SURVITEC LIFE RAFT TEST AND SURVEY REPORT

Date: 2021-10-21 | Station N°: 50403 | Reinspection certificate N°: -

Life raft maker	RFD	Ships name	Linda AF Helsingborg
Type of life raft	Surviva MK IV	Owner	Hartford Rederi AB
Capacity	25	Flag state	Sweden
Serial #	5086310222561	IMO No	-
Pack	Solas B	Last service	09-2020
Date of manufacture	09-2018	Call sign	-
HRU type / n °			

OVERPRESSURE VALVE				PRESSURE TEST (WP TEST)					
LOWER		UPPER			Time	T*	A*	Lower buoyancy (millibars)	Upper buoyancy (millibars)
Opening	Reseat	Opening	Reseat	Starting	09:30	18.8	-	238	242
276	238	272	242	End	10:30	19.1	-	232	238
				Difference after correction				-2.18%	-2.56

T* = Temperature - A* = Atmospheric

		Tests done	Yes	No
Cylinder N°	18w051102			
CO2 weight	10.770			
N2 weight	0.540	NAP test		✘
Full weight	31.654	GI test		✘
Weight reading	OK	Floor seam test		✘
Last hydro test	03-2018	Over load test (DL)		✘
Cylinder refilling	No	Cyl. hydro test		✘
OP head type/#	Leafield GIST	Hoses changed		✘

Main buoyancy	Check	R*	Canopy	Check	R*	Inner floor	Check	R*
Buoyancy	✔		Canopy	✔		Automatic bailer	—	
Lifeline outer	✔		Reflective tape	✔		Vacuum breaker	—	
Lifeline inner	✔		Rainwater collector	✔		Insulating foam	✔	
Painter patch	✔		Entrances	✔		**Outer floor**	**Check**	**R***
Towing patch	✔		External flash light	✔		Reflective tape	✔	
Bowsing lines	—		Arches	✔		Water pockets	✔	
Ramp / Ladder	✔		Shackle (DL)	—		CO2 cylinder pockets	✔	
OP valves	✔		Webbings (DL)	—		Righting straps	✔	
OP valves cap	✔							
Labels	✔		**Container / Valise**	**Check**	**R***	**Inflation system**	**Check**	**R***
Floating knife	✔		Upper shell	✔		Inlet valves	✔	
Sea anchor	✔		Lower shell	✔		No return valve arch	—	
Quoit + line	✔		Foam/Plastic	replacement SE-79056A	✘	No return valve ramp	—	
Reflective tape	✔		Painter line	check 18/28m	✘	Hoses	✔	
Signal card	✔		Labels	✔		Inflation valve	✔	
Immed. actions card	✔		Identification tube	✔				

R* = Replacement

Equipment	Check	R*	Expiry date
Pack			
Hand flare	✔		08-2023
Rocket parachute	✔		08-2023
Smoke signal	✔		08-2023
Food	—		
Drinking water	—		
First aid kit	replacement ZOD-Z63703 210226	✘	09-2024
Seasickness tablet	✔		11-2022
Battery for torch	replacement 4x LS-AM2	✘	
Repair kit (glue)	✔		10-2022
HRU	—		
Epirb	—		
Outside pack			
Flash light battery	✔		04-2023
Internal light	✔		05-2023
Transponder radar	—		
P.P. Straps	replacement 8x RFD-41423001	✘	
Diaphragm	✔		
Environmental Charge	✔		

Other equipment	Check	R*
Leak stopper	✔	
Bellow	✔	
Bailer	✔	
Sponge	✔	
Tin opener	—	
Fishing kit	—	
Torch	✔	
Spare bulb	✔	
Signal mirror	✔	
Whistle	✔	
Drinking vessel	✔	
Seasickness bag	✔	
Sea anchor	✔	
Paddles	✔	
Rainwater collector	✔	
Servicing history	✔	
T.P.A.	✔	
Radar reflector	check Chemring	✘

Additional	Check	R*	Additional	Check	R*
Label	replacement 2x RFD-20765001	✘	Painter Block	replacement RFD-20883001	✘

LIFE RAFT AND EQUIPMENT CONDITION INFORMATION

	Yes	No		Yes	No
Was raft wet?		✘	Was life raft damaged?		✘
Was container damaged?		✘	Had life raft been inflated at sea?		✘

Description:

REPACKING

DOCUMENTS	
Life raft label completed	✔
ID card completed	✔
Reinspection certificate completed	✔

CONNECTIONS	
Flashlight battery connected	✔
Internal light connected	✔
Painter line attached	✔
Controlled by (signature)	Gideon Hayden

DOCUMENTS	
Container label completed	✔
Servicing history completed	✔

FOR LIFE RAFTS EQUIPPED WITH VENTURI	
Venturis opened/secured	—
Flap covers installed	—
Venturis caps removed	—

Station n°: 50403 Technician name: John Björkman Visa: 11577